

From: The Stewards  
To: All FGTWC Competitors  
Re: Article 29.20

Bulletin No: **GTWC-02 Revised**  
Date: 9 Apr 2024  
Time: 21:25

The Stewards have received a report from the Technical Manager regarding the functionality of the TPMS system for GMG Racing Car #32.

The report showed the system was not functional during Race 1 of the Event.

The Stewards apply a penalty of moving Car #32 to the last finishing position. **No points will be awarded to any Competitor/Driver for any eligible Championship.**



Scot Elkins  
Steward – Chairman



Coy Arbour  
Steward



Elliot Forbes Robinson  
Steward